

Appendix C - Site Photos



Figure A: Nearby house. (See map)



Figure B: Gabion below house. (See map)



Figure C: Fence line bordering Erf4571 and Erf4350



Figure D: Existing path leading up to hilltop. (See map)



Figure E: Existing pipeline. (See map)



Figure F: Existing pipeline. (See map)



Figure G: View from hilltop.



Figure H: View of valley and house from hilltop.



Figure I: View of pipeline from hilltop.



Figure J: View of Isazane informal housing.




Figure K: View of western stream from hilltop. (See map).



Figure L: Western stream.



Figure M: View of hilltop from western stream.



Figure N: On site vegetation



Figure O: On site vegetation




Figure 1: Map of Proposed Alternative Layouts